

Message

From: Randell, George [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=70FE10E8F4FA4943BF81F6C2C3530E37-GRANDELL]
Sent: 8/21/2014 4:09:13 PM
To: Irwin, Barb J [Barb.J.Irwin@dynegy.com]
CC: Rosegay, Margaret [margaret.rosegay@pillsburylaw.com]
Subject: RE: Lab Reports 5 of 6

Hello Barb, so after a cursory re3viw everything looks good except for sample SBPP-176-072314 in lab report 1720. Aroclor 1242 is upwards of 5.6ppm pcbs. It is not in the lab report and I read the blurb on why. However, the blurb does not provide enough information. I would like to know if you know where the sample came from, does further investigation need to occur, and why is the sample so much higher than the rest of the samples. Please email or give me a call at your earliest convenience.

George Randell

Waste Management Division
U.S. EPA
75 Hawthorne Street
San Francisco, CA 94105
(415) 972-3439

From: Irwin, Barb J [mailto:Barb.J.Irwin@dynegy.com]
Sent: Thursday, August 21, 2014 8:10 AM
To: Randell, George
Subject: Lab Reports 5 of 6

14-07-1720
14-07-1728

Barb Irwin

Director Environmental
Dynegy Operating Company

Cell: 217-519-4035
e-mail: barb.irwin@dynegy.com

Dynegy South Bay, LLC
990 Bay Blvd.
Chula Vista, CA 91911

From: Irwin, Barb J
Sent: Thursday, August 21, 2014 8:08 AM
To: 'Randell, George'
Subject: Lab Reports 4 of 6

14-07-0476
14-07-1536

Barb Irwin

Director Environmental
Dynegy Operating Company

Cell: 217-519-4035
e-mail: barb.irwin@dynegy.com

Dynegy South Bay, LLC
990 Bay Blvd.
Chula Vista, CA 91911

From: Irwin, Barb J
Sent: Thursday, August 21, 2014 8:07 AM
To: 'Randell, George'
Subject: Lab Reports 3 of 6

14-04-2162
14-07-0294

Barb Irwin
Director Environmental
Dynegy Operating Company

Cell: 217-519-4035
e-mail: barb.irwin@dynegy.com

Dynegy South Bay, LLC
990 Bay Blvd.
Chula Vista, CA 91911

From: Irwin, Barb J
Sent: Thursday, August 21, 2014 8:06 AM
To: 'Randell, George'
Subject: RE: Lab Reports 2 of 6

14-03-0924
14-03-1365

Barb Irwin
Director Environmental
Dynegy Operating Company

Cell: 217-519-4035
e-mail: barb.irwin@dynegy.com

Dynegy South Bay, LLC
990 Bay Blvd.
Chula Vista, CA 91911

From: Irwin, Barb J
Sent: Thursday, August 21, 2014 7:29 AM
To: 'Randell, George'
Cc: Rosegay, Margaret
Subject: Lab Reports 1 of 6

14-01-0924
14-01-0923

Barb Irwin
Director Environmental

Dynegy Operating Company

Cell: 217-519-4035

e-mail: barb.irwin@dynegy.com

Dynegy South Bay, LLC

990 Bay Blvd.

Chula Vista, CA 91911